

## **Safety Recall Quarterly Report Information**

**Per 49 CFR Part 573.6**

**Report Date: July 28, 2000**

**Calendar Quarter: II '00**

**Safety Recall Quarterly Report from Apr. 1, 2000 through June 30, 2000**

**Manufacturer: Bayerische Motoren Werke AG (BMW AG)**

**Report Author: William Scully**

**Phone: (201) 573-2069**

**Report Number: 1**

**Recall Subject: Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. **NHTSA Safety Recall Campaign No.: 00V-048**
2.
  - (a) **The date notification to purchasers began: May 15, 2000**
  - (b) **The date notification to purchasers was completed: May 15, 2000**
3. **The total number of items involved: 17,766**  
**Number of Items Returned from Inventory or Remedied Prior to Sale: 0**
4.
  - (a) **Total number inspected & remedied: 5,531**
  - (b) **Total number inspected & NOT REQUIRING REMEDY: 0**
5. **Items Determined to be Unreachable:**

<b>Total number exported:</b>	<b>0</b>
<b>Total number stolen:</b>	<b>1</b>
<b>Total number scrapped:</b>	<b>0</b>
<b>Total number unable to notify:</b>	<b>469</b>

## **Safety Recall Quarterly Report Information**

**Per 49 CFR Part 573.6**

**Report Date: October 27, 2000** **Calendar Quarter: III '00**

**Safety Recall Quarterly Report from July 1, 2000 through Sept. 30, 2000**

**Manufacturer: Bayerische Motoren Werke AG (BMW AG)**

**Report Author: William Scully** **Phone: (201) 573-2069**

**Report Number: 2**

**Recall Subject: Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-series**

- 1. NHTSA Safety Recall Campaign No.: 00V-048**
- 2. (a) The date notification to purchasers began: May 15, 2000**  
**(b) The date notification to purchasers was completed: May 15, 2000**
- 3. The total number of items involved: 17,778**  
**Number of Items Returned from Inventory or Remedied Prior to Sale: 0**
- 4. (a) Total number inspected & remedied: 8,997**  
**(b) Total number inspected & NOT REQUIRING REMEDY: 0**
- 5. Items Determined to be Unreachable:**

<b>Total number exported:</b>	<b>0</b>
<b>Total number stolen:</b>	<b>1</b>
<b>Total number scrapped:</b>	<b>0</b>
<b>Total number unable to notify:</b>	<b>469</b>

**Safety Recall Quarterly Report Information**

**Per 49 CFR Part 573.6**

**Report Date: January 29, 2001**

**Calendar Quarter: IV '00**

**Safety Recall Quarterly Report from Oct. 1, 2000 through Dec. 31, 2000**

**Manufacturer: Bayerische Motoren Werke AG (BMW AG)**

**Report Author: William Scully**

**Phone: (201) 673-2069**

**Report Number: 3**

**Recall Subject: Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. **NHTSA Safety Recall Campaign No.: 00V-048**
2. (a) **The date notification to purchasers began: May 15, 2000**  
(b) **The date notification to purchasers was completed: May 15, 2000**
3. **The total number of items involved: 17,789**  
**Number of Items Returned from Inventory or Remedied Prior to Sale: 0**
4. (a) **Total number inspected & remedied: 12,711**  
(b) **Total number inspected & NOT REQUIRING REMEDY: 0**
5. **Items Determined to be Unreachable:**

<b>Total number exported:</b>	<b>0</b>
<b>Total number stolen:</b>	<b>2</b>
<b>Total number scrapped:</b>	<b>1</b>
<b>Total number unable to notify:</b>	<b>470</b>

## **Safety Recall Quarterly Report Information**

Per 49 CFR Part 573.6

Report Date: **April 27, 2001**

Calendar Quarter: **I '01**

Safety Recall Quarterly Report from **Jan. 1, 2001** through **Mar. 31, 2001**

Manufacturer: **Bayerische Motoren Werke AG (BMW AG)**

Report Author: **William Scully**

Phone: **(201) 573-2089**

Report Number: **4**

Recall Subject: **Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. NHTSA Safety Recall Campaign No.: **00V-048**
2. (a) The date notification to purchasers began: **May 15, 2000**  
(b) The date notification to purchasers was completed: **May 15, 2000**
3. The total number of items involved: **17,795**  
Number of Items Returned from Inventory or Remedied Prior to Sale: **0**
4. (a) Total number inspected & remedied: **14,330**  
(b) Total number inspected & NOT REQUIRING REMEDY: **0**
5. Items Determined to be Unreachable:

Total number exported:	<b>0</b>
Total number stolen:	<b>2</b>
Total number scrapped:	<b>1</b>
Total number unable to notify:	<b>470</b>

## **Safety Recall Quarterly Report Information**

**Per 49 CFR Part 573.6**

**Report Date: July 30, 2001**

**Calendar Quarter: II '01**

**Safety Recall Quarterly Report from Apr. 1, 2001 through June 30, 2001**

**Manufacturer: Bayerische Motoren Werke AG (BMW AG)**

**Report Author: William Scully**

**Phone: (201) 673-2069**

**Report Number: 5**

**Recall Subject: Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. **NHTSA Safety Recall Campaign No.: 00V-048**
2. (a) **The date notification to purchasers began: May 15, 2000**  
(b) **The date notification to purchasers was completed: May 15, 2000**
3. **The total number of items involved: 17,803**  
**Number of Items Returned from Inventory or Remedied Prior to Sale: 0**
4. (a) **Total number inspected & remedied: 15,436**  
(b) **Total number inspected & NOT REQUIRING REMEDY: 0**
5. **Items Determined to be Unreachable:**

<b>Total number exported:</b>	<b>0</b>
<b>Total number stolen:</b>	<b>2</b>
<b>Total number scrapped:</b>	<b>1</b>
<b>Total number unable to notify:</b>	<b>470</b>

## **Safety Recall Quarterly Report Information**

Per 49 CFR Part 573.6

**Report Date: July 30, 2001**

**Calendar Quarter: II '01**

**Safety Recall Quarterly Report from Apr. 1, 2001 through June 30, 2001**

**Manufacturer: Bayerische Motoren Werke AG (BMW AG)**

**Report Author: William Scully**

**Phone: (201) 573-2069**

**Report Number: 5**

**Recall Subject: Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. **NHTSA Safety Recall Campaign No.: 00V-048**
2. (a) **The date notification to purchasers began: May 15, 2000**  
(b) **The date notification to purchasers was completed: May 15, 2000**
3. **The total number of items involved: 17,803**  
**Number of items returned from inventory or remedied prior to sale: 0**
4. (a) **Total number inspected & remedied: 15,436**  
(b) **Total number inspected & NOT REQUIRING REMEDY: 0**
5. **Items Determined to be Unreachable:**

<b>Total number exported:</b>	<b>0</b>
<b>Total number stolen:</b>	<b>2</b>
<b>Total number scrapped:</b>	<b>1</b>
<b>Total number unable to notify:</b>	<b>470</b>

## **Safety Recall Quarterly Report Information**

Per 49 CFR Part 573.6

Report Date: **October 26, 2001**

Calendar Quarter: **III '01**

Safety Recall Quarterly Report from **July 1, 2001** through **Sept. 30, 2001**

Manufacturer: **Bayerische Motoren Werke AG (BMW AG)**

Report Author: **William Scully**

Phone: **(201) 573-2069**

Report Number: **6**

Recall Subject: **Brake Lamp Switch, 2000 BMW 3-, 5-, and 7-carlines**

1. NHTSA Safety Recall Campaign No.: **00V-048**
2. (a) The date notification to purchasers began: **May 15, 2000**  
(b) The date notification to purchasers was completed: **May 15, 2000**
3. The total number of items involved: **17,808**  
Number of Items Returned from Inventory or Remedied Prior to Sale: **0**
4. (a) Total number inspected & remedied: **16,013**  
(b) Total number inspected & NOT REQUIRING REMEDY: **0**
5. Items Determined to be Unreachable:

Total number exported:	<b>0</b>
Total number stolen:	<b>2</b>
Total number scrapped:	<b>1</b>
Total number unable to notify:	<b>470</b>